

FIG. 4







FIG. 5











FIG. 9a

918	920	922	924			926
HEADER	ROUTING	SENDING UNIT ID	RECEIVING UNIT ID	•••	• • •	END OF PACKET

FIG. 9b









FIG. 10b





ROAMING HIST	ORY FO	R EE06BB06		
TIME (GM	(I)	NETWORK	STATUS	POWER SAVE
1999-10-23.04:10		47	IN SERVICE	YES
1999-10-23.02:2	26	47	OUT OF SERVICE	YES
1999-10-23.02:2	26	47	IN SERVICE	YES
1999-10-23.02:2	25	47	OUT OF SERVICE	YES
1999-10-22.23:3	31	47	IN SERVICE	YES
1999-10-22.23:1	19	12	IN SERVICE	YES
1999-10-22.20:1	16	47	IN SERVICE	YES
1999-10-22.20:1	13	12	IN SERVICE	YES
1999-10-22.18:5	55	47	IN SERVICE	YES
1999-10-22.18:4	47	12	IN SERVICE	YES
1999-10-22.13:1	15	47	IN SERVICE	YES

FIG. 12



STATISTIC	
GOOD PDUs RECEIVED BY MODEM	:3
BAD PDUs RECEIVED BY MODEM	:0
RESPONSE PDUs RECEIVED BY MODEM	:3
PDUs SENT BY MODEM	:3
PDUs SENT BY MODEM (WITH RETRIES)	:3
BLOCKS SENT BY MODEM	:9
BLOCKS SENT BY MODEM (SQUARED)	:33
REGISTRATION REQUESTS SENT BY MODEM	:3
RESPONSE PDUs SENT BY MODEM	:3 .

FIG. 13